



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: October 14, 2008

Reviewed:

| | |
|--|-----------------------------|
| Mine Name: Red Emerald | Permit Number: M010058 |
| Operator Name: Red Emerald Inc. | Inspection Date: 10/03/2008 |
| Inspector(s): Brett Gregory (for Tom Munson) | Time: 8:30 am |
| Other Participants: None | Mine Status: Active |

| Elements of Inspection | Evaluated | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Water Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Re-vegetation | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Air Quality | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Bond Amount: \$55,200

Permit fee: Delinquent. Gaylan Cropper (435-979-2023) was contacted on December 9, 2008 regarding delinquent fees.

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary:

1. This years annual permit fees have not been paid in the amount of \$500. Gaylan Cropper (435-979-2023) was contacted on December 9, 2008 regarding delinquent fees.

6. Areas that are not being mined should undergo concurrent reclamation.

10. The weed Halogeton is growing in the overburden piles and should be controlled.

Conclusions and Recommendations:

It has been brought to our attention that the person listed as contact for the site is no longer available at the phone number in our database. I contacted Gaylan Cropper (435-979-2023) regarding permit fees and obtaining a new phone number for Dick Turner. Dick Turner was contacted and his phone number and address were changed to reflect updated information. Mr. Turner stated the fees would be paid immediately. The operator is also required to contact the Division with future plans for the site, present plans for controlling weeds and commencing reclamation of areas not being used.

Inspector's Signature

TM:BG:vs

cc: (OPERATOR)

ed_ginouves@blm.gov

O:\M001-Beaver\M0010058-RedEmerald\draft\insp-10032008.doc



Widespread areas of Halogeton.



Halogeton.



Central mine area.



Falling rock hazard.